



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

0001

### Inspection Report

#### Minerals Regulatory Program

February 14, 2008

Supervisor DBZ

**Mine Name:** Montello Mine  
**Operator Name:** Interstate Brick Co.

**Permit number:** M/003/0004  
**Inspection Date:** May 2, 2007  
**Time:** 12:00 noon

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** Tony Peck  
**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

This site was active during this inspection. The company had recently shot the highwall, and during this inspection, they were using a excavator and a dozer to remove the loose material from the highwall bench, by pushing it down. A loader was moving this material to a stockpile or loading trucks.

There has not been any expansion of the disturbed area. The access road was in fair condition – there were a few places that needed maintenance to smooth out ruts and potholes.

A fuel truck had been brought in to fuel equipment.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Continue to monitor the site when in the area.

**Inspector's Signature** [Signature]

LK:pb

O:\M003-BoxElder\M0030004-Montello\inspections\Insp-05022007.doc

0001